

PCN Title Affected Products	Mako G surface treatment change to black powder coating Mako G camera family		
PCN Number	PCR-2017-03-05	PCN Issue date	2017-July-20 Updated Dec. 04
Contact	Inside Sales Team		
Change Type			
<ul> <li>Regulatory / Compliance</li> <li>Mechanical Specification</li> <li>Electrical Specification</li> <li>Optical Specification</li> </ul>	<ul> <li>Firmware Specification</li> <li>Accessories Specification</li> <li>Discontinued</li> <li>Component Change</li> </ul>		


### Affected Products


All Mako G camera models and modular concept options

#### **Change Description**

The Mako housing (back plate, bottom plate, and front flange) surface treatment will be changed from nickel plating to black powder coating. The change is cosmetic and will not have a negative effect on the image quality or camera performance. There are a slight dimension increases (<0.2 mm), see Figure 1 and Figure 2 below for a detailed comparison of the legacy and new finishes.

This housing change is effective from SN 536905675 onwards.







## Mako with silver nickel plating surface



# Mako with black powder coating surface



## Figure 2 – Front flange and back plate vs. bottom plate: housings with legacy silver nickel plating vs. new black powder coating

### **Reason for Change**

Aesthetic change to be consistent with our brand identity and match the colors of our other existing lineup of cameras

### Possible successor

Since this is not a discontinuation the item numbers for the affected Mako cameras do not change and will still be available. Therefore, no successor is needed.

The information provided in this PCN notification are subject to change without notice. For the latest version of this document, please visit the Allied Vision <u>website</u>.

### Support:

In case of technical questions please contact our <u>Support Team</u>

## General inquiries:

Please contact our Inside Sales Team