

**Affected Product** Fiber optics cables LC-LC  
**PCN Title** Discontinuation Fiber optics cable  
**PCN No.** 2020-02-19 **PCN Issue date** 2020-02-19

**Type of change**

- |   |   |
|---|---|
| <input type="checkbox"/> Regulatory / Compliance  | <input type="checkbox"/> Firmware Specification         |
| <input type="checkbox"/> Mechanical Specification | <input type="checkbox"/> Accessories Specification      |
| <input type="checkbox"/> Electrical Specification | <input checked="" type="checkbox"/> DISC (Discontinued) |
| <input type="checkbox"/> Optical Specification    | <input type="checkbox"/>                                |

**Affected item number(s)**

K1200095	Fiber optic, 10 m	MM 62.5/125µm, LC-LC connector, indoor
K1200087	Fiber optic, 30 m	MM 62.5/125µm, LC-LC connector, indoor
K1200085	Fiber optic, 50 m	MM 62.5/125µm, LC-LC connector, indoor
K1200086	Fiber optic, 100 m	MM 62.5/125µm, LC-LC connector, indoor
K1200088	Fiber optic, 150 m	MM 62.5/125µm, LC-LC connector, indoor

**Reason for change**

The supply chain for the products has been terminated.

**Change description**

The above-mentioned items can not be sourced anymore and switch over to status "discontinued". Remaining stock can be purchased.

**Customer action request**

Check final demand. Orders will be confirmed, based on available stock

**Possible successor**

n/a

For more specific details and more alternative products, please contact your Allied Vision Support or Sales representative.

**Support:**

[support@alliedvision.com](mailto:support@alliedvision.com)

**General inquiries:**

[info@alliedvision.com](mailto:info@alliedvision.com)