

| | | | |
|-------------------|-----------------------------------|----------------|--|
| PCN Title | FH55 Retaining Plate add on | | |
| Affected Products | Alvium CSI-2 cameras | | |
| PCN Number | PCN2025-10-08 | PCN Issue date | 08.10.2025 11.11.2025 (document update) |
| Contact | Inside Sales Team | | |

Change Classification

Minor

Change Type

Add on

Affected Products

All Alvium CSI-2 models

Change Description

Every CSI-2 camera is now delivered with an FH55 retaining plate to increase protection of the CSI-2 connector.

Reason for Change

Every Alvium CSI-2 camera now includes an FH55 retaining plate for enhanced FPC cable and connector protection and reliability during evaluation. For permanent installations we still recommend to implement a strain relief per the user guide recommendations.

Impact / Possible Successor

Additional part included with every Alvium CSI-2 camera

First Ship Date

20.10.2025

The information provided in this product change notification are subject to change without notice.
For the latest version of this document, please visit the Allied Vision [website](#).

Support:In case of technical questions please contact our [Support Team](#)**General inquiries:**Please contact our [Inside Sales Team](#)